



FIN: WDC 253315 1F 734291

## Current advice for the vehicle:

none

## Outstanding KDM:

none

## ESKULAB decisions:

none

## Damage history:

| Typ | Rep. Date  | X  | #  | Damage code | Damage code description                                                            | Claim No. | L-KZ | Area  | LL    | M  | E C | Credit note no. | Credit note date |
|-----|------------|----|----|-------------|------------------------------------------------------------------------------------|-----------|------|-------|-------|----|-----|-----------------|------------------|
|     | 29.09.2022 | AA | 24 | 000012SV7   | Service scope, Service A Service contract                                          | 123282    | D    | 02933 | 45915 | km | 1   | 000001222       | 07.10.2022       |
|     | 29.09.2022 | AB | 23 | 082023SV7   | Wiper blade, front Service contract                                                | 123282    | D    | 02933 | 45915 | km | 1   | 000001222       | 07.10.2022       |
|     | 29.09.2022 |    | 22 | 000791SV8   | Vehicle inspection according to requirements of trade association Service contract | 123282    | D    | 02933 | 45915 | km | 1   | 000001222       | 07.10.2022       |
|     | 29.09.2022 |    |    |             | Service minor - Regular service                                                    | AU123282  | D    | 02933 | 45915 | km |     |                 |                  |
|     | 28.07.2022 |    | 21 | 042214D17   | Brake lining, rear Worn                                                            | 122579    | D    | 02933 | 42602 | km | 1   | 000001212       | 29.07.2022       |
|     | 21.04.2022 |    | 20 | 020900087   | 21P2090008                                                                         | 121426    | D    | 02933 | 38289 | km | 1   | 000001200       | 06.05.2022       |
|     | 21.04.2022 |    | 19 | 082368EA7   | Central display, instrument panel No display                                       | 300790    | D    | 02933 | 38289 | km | 1   | 000001200       | 06.05.2022       |
|     | 29.03.2022 | AC | 18 | 000515SV8   | Wheel replacement w/o balancing (service contract) Service contract                | 023573    | D    | 22954 | 33406 | km | 1   | 000001234       | 30.12.2022       |
|     | 29.03.2022 | AD | 17 | 000701SV8   | Storage, Ground Service contract                                                   | 023573    | D    | 22954 | 33406 | km | 1   | 000001234       | 30.12.2022       |
|     | 08.11.2021 |    | 16 | 000011SV7   | Service scope, Service B Service contract                                          | 020400    | D    | 22954 | 33390 | km | 1   | 000001175       | 12.11.2021       |
|     | 08.11.2021 | AC | 15 | 000515SV8   | Wheel replacement w/o balancing (service contract) Service contract                | 020400    | D    | 22954 | 33390 | km | 1   | 000001175       | 12.11.2021       |
|     | 08.11.2021 | AD | 14 | 000701SV8   | Storage, Ground Service contract                                                   | 020400    | D    | 22954 | 33390 | km | 1   | 000001175       | 12.11.2021       |
|     | 08.11.2021 |    |    |             | Service major - Regular service                                                    | AU020400  | D    | 22954 | 33390 | km |     |                 |                  |
|     | 21.04.2021 | AC | 13 | 000515SV8   | Wheel replacement w/o balancing (service contract) Service contract                | 039836    | D    | 22954 | 25869 | km | 0   | 000000000       | 30.04.2021       |
|     | 21.04.2021 | AD | 12 | 000701SV8   | Storage, Ground Service contract                                                   | 039836    | D    | 22954 | 25869 | km | 0   | 000000000       | 30.04.2021       |
|     | 19.10.2020 | AC | 11 | 000515SV8   | Wheel replacement w/o balancing (service contract) Service contract                | 034878    | D    | 22954 | 22737 | km | 0   | 000000000       | 18.12.2020       |
|     | 19.10.2020 | AD | 10 | 000701SV8   | Storage, Ground Service contract                                                   | 034878    | D    | 22954 | 22737 | km | 0   | 000000000       | 18.12.2020       |
|     | 25.09.2020 | AA | 9  | 000012SV7   | Service scope, Service A Service contract                                          | 034002    | D    | 22954 | 21196 | km | 0   | 000000000       | 02.10.2020       |
|     | 25.09.2020 | AB | 8  | 082023SV7   | Wiper blade, front Service contract                                                | 034002    | D    | 22954 | 21196 | km | 0   | 000000000       | 02.10.2020       |
|     | 25.09.2020 |    |    |             | Service minor - Regular service                                                    | AU034002  | D    | 22954 | 21196 | km |     |                 |                  |



## Vehicle Information (Damage history)

52602

| Typ | Rep. Date  | X  | # | Damage code | Damage code description                                             | Claim No. | L-KZ | Area  | LL    | M  | E C | Credit note no. | Credit note date |
|-----|------------|----|---|-------------|---------------------------------------------------------------------|-----------|------|-------|-------|----|-----|-----------------|------------------|
|     | 01.07.2020 | AD | 7 | 000701SV8   | Storage, Ground Service contract                                    | 097626    | D    | 22954 | 15000 | km | 0   | 000000000       | 22.01.2021       |
|     | 28.04.2020 | AD | 6 | 000701SV8   | Storage, Ground Service contract                                    | 030129    | D    | 22954 | 11929 | km | 0   | 000000000       | 15.01.2021       |
|     | 28.04.2020 | AC | 5 | 000515SV8   | Wheel replacement w/o balancing (service contract) Service contract | 030129    | D    | 22954 | 11929 | km | 0   | 000000000       | 01.05.2020       |
|     | 24.02.2020 |    | 4 | 08251B528   | Control unit, parking system Does not operate correctly             | 028599    | D    | 22954 | 10049 | km | 0   | 000000000       | 28.02.2020       |
|     | 24.02.2020 | AE | 3 | 0820D3508   | Multifunction camera, stereo Shows incorrect readings               | 028599    | D    | 22954 | 10049 | km | 0   | 000000000       | 28.02.2020       |
|     | 24.02.2020 | AE | 2 | 0820D3M38   | Multifunction camera, stereo Pickup and delivery service            | 028599    | D    | 22954 | 10049 | km | 0   | 000000000       | 28.02.2020       |
|     | 18.12.2019 |    | 1 | 063126387   | Tank filler recess Loose                                            | 026601    | D    | 22954 | 5799  | km | 0   | 000000000       | 03.01.2020       |